

State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:						
OGM	Mark Reynolds Resident Agent					
OGM	Pete Hess Environmental Scientist III					

Inspection Report

Permit Number:	C0070011 PARTIAL		
Inspection Type:			
Inspection Date:	Friday, May 16, 2008		
Start Date/Time:	5/16/2008 8:45:00 AM		
End Date/Time:	5/16/2008 11:35:00 AM		
Last Inspection:	Friday, April 18, 2008		

Inspector: Pete Hess, Environmental Scientist III

Weather: Warm and clear.

InspectionID Report Number: 1642

_ Accepted by: jhelfric

Monday, June 02, 2008

Date

Permitee: HIAWATHA COAL CO INC Operator: HIAWATHA COAL CO INC

Site: HIAWATHA MINE COMPLEX

Address: PO BOX 1245, HUNTINGTON UT 84528

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

12,177.00	Total Permitted		
290.00	Total Disturbed		
	Phase I		
	Phase II		
	Phase III		

Mineral Ownership

Types of Operations ✓ Federal ✓ Underground State □ Surface Loadout County Processing Other ☐ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Mr. Shawn Baker also took part in today's inspection, representing the Permittee.

Inspector's Signature:

Pete Hess, Environmental Scientist III

Inspector ID Number: 46

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070011 Inspection Type: PARTIAL

Inspection Date: Friday, May 16, 2008

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓			
3.	Topsoil	✓			
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		✓	
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage	✓		✓	
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.Ł	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070011
Inspection Type: PARTIAL

Inspection Date: Friday, May 16, 2008

Page 3 of 3

7. Coal Mine Waste, Refuse Piles, Impoundments

An erosion rill was observed on the south slope of the recalimed slurry pond #5; Mr. Reynolds and Mr. Baker placed native rock from the area to fill the rill and reduce further erosion of the rill. The water which reports from this slope to ditch DD2 at the toe reports to pond #7.

10. Slides and Other Damage

A large erosion cut was observed at the crest of the slope just west of catch basin #4, inside the railroad right-of-way. Mr. Reynolds agreed to repair this cut by backfilling, with the understanding that the repair was not Hiawatha Coal Company's responsibility. A deep cut was also observed in ditch DD6, which is on the east side of refuse pile #2. The gradient of the ditch is the cause of this cut, and the Permittee, in conjunction with the Division, suggested that at least four rock gabions be installed along the cut length to reduce further erosive action, by slowing the flow velocity and allowing sediment to build upgradient of the gabions. Hiawatha Coal Company is proceeding with this construction. A fourth area where erosive action has occurred is directly north of the outlet of the 24 inch CMP (#1) in the ditch which reports into the slurry pond 5A depression. This cutting has occurred in coal material, and is not considered by this person to be a problem. All sediment reports to a containment, and the erosion has not affected soil resources or vegetation. The ditch bottom contains a small amount of fair sized creek stone to reduce erosive effect.